

City of Baltimore Wet Weather Consent Decree Smoke and Dyed Water Testing Form

Page 1 of 1

Sewershed: Gwynns Falls

Company: Savin

Date: 4/23/2009

Test to be performed:

Smoke ☐ Dyed Water ☒

Ground Condition:

Dry ☒ Damp ☐ Wet ☐

Supervisor: JAW


Manhole_ID: S04A_026MH

Test ID: D1032-019003

Notification Made: NA

(Residents, Fire, 311)

Field Sketch: Show all manholes with Numbers, Blower Placement Locations, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photo Numbers.



Defect Loc	Obs_ClockFrom	Obs_ClockTo	Observation	Obs_Remarks
0			Start of Survey	
0			Manhole	S04A_026MH
0			Water Level	
0			Dye Test Visible	WALL OF MANHOLE, 0.5 gpm
0			Dye Test Visible	WALL OF MANHOLE 1 gpm
3			Dye Test Visible	@ jt, 8gpm
3	07	08	Fracture Circumferential	
3	07	08	Infil Runner	FC
3	03	09	Infil Runner	
5.099999905			Abandoned Survey	NO MORE DYE VISIBLE